

# Assembly Instructions - Adapter Bracket for Hitachi® Plasma model 4201U

Models: PLP 4201U

Two Instruction sheets are included with this product. Begin with this sheet.




This product is intended for use with UL Listed products and must be installed by a qualified professional installer.

**Maximum Load Capacity:**  
150.0 lb (68.2 kg)


## Parts List

Description	Qty.	Part No.
<b>AA</b> adapter plate	1	200-1426
<b>BB</b> M6 x 10 mm serrated socket-pin screw	8	510-1066
<b>CC</b> 4mm security allen wrench	1	560-9646


**AA**



**BB**



**CC**



Note: Actual parts may appear slightly different than illustrated.

**IMPORTANT! Read entire instruction sheet before you start installation and assembly.**

- 1 Attach adapter bracket (**AA**) to back of plasma using eight M6 screws (**BB**). Use security allen wrench (**CC**) to tighten screws.

